



ADDENDUM NO. 1

REQUEST FOR PROPOSALS 2020-125

Kitsap County Public Works Department, Solid Waste Division

TO: All Respondents

FROM: Vicki Martin, Buyer

CLOSING DATE: Thursday, November 19, 2020 at 3:00 p.m. (UNCHANGED)

REF NO.: RFP 2020-125 – Solid Waste Transfer Station Operation and Maintenance, and Waste Transport and Disposal Services

DATE: Tuesday, August 18, 2020

Revisions made to Attachment A Mandatory Pre-Proposal Meeting and Site Tour Information.

1. Replace Attachment A Mandatory Pre-Proposal Meeting and Site Tour Information with the following:

The mandatory pre-proposal meeting and site tour will be held on **Wednesday, August 26, 2020**. The site visit will begin at 10:00 a.m. at the Randy W. Casteel Public Works Annex, located at 8600 SW Imperial Way, Bremerton, Washington 98312, in the Olympic View Industrial Park, and will then proceed as a group to OVTS after a brief introduction and overview. Directions are provided below.

Personal protective equipment (PPE) including hard hat, safety vest, safety glasses, and closed-toe shoes are required and must be worn while onsite at OVTS. Those attending should provide their own PPE for the site visit. Attendees will also be responsible for following any requirements or recommendations in place at the time of the site visit for protection from COVID-19.

Directions from the North (Silverdale/Bremerton):

Take Highway 3 South into Gorst. Exit right onto Highway 3 South towards Belfair/Shelton. As you approach the Bremerton National Airport, take Exit 28 at SW Barney White Road and enter the Olympic View Industrial Park. At the four-way stop, continue straight through the intersection and follow SW Barney White Road to the next intersection with SW Imperial Way. The Randy W. Casteel Public Works Annex is located on the southwest corner of the intersection.

Directions from the South (Tacoma/Gig Harbor):

Take Highway 16 West towards Bremerton/Port Orchard. As you enter Gorst, exit left onto Highway 3 South towards Belfair/Shelton. Follow the exit towards the stop light and turn left onto Highway 3 South. Continue on Highway 3 South towards Belfair. As you approach

the Bremerton National Airport, take Exit 28 at SW Barney White Road and enter the Olympic View Industrial Park. At the four-way stop, continue straight through the intersection and follow SW Barney White Road to the next intersection with SW Imperial Way. The Randy W. Casteel Public Works Annex is located on the southwest corner of the intersection.

Directions from the East (Shelton/Belfair):

Take Highway 3 North towards Bremerton/Port Orchard. As you approach the Bremerton National Airport, make a left at the light for SW Imperial Way and enter the Olympic View Industrial Park. At the four-way stop, go left onto SW Barney White Road and follow SW Barney White Road to the next intersection with SW Imperial Way. The Randy W. Casteel Public Works Annex is located on the southwest corner of the intersection.

Directions from the Seattle/Bremerton Ferry Terminal:

Follow the ferry traffic south onto Burwell Street (State Route 304 N). As you emerge from the tunnel, continue on South 304 for approximately 1.5 miles through several traffic lights. Turn left onto N Callow Ave (State Route 304 S) and continue to Highway 3 South toward Belfair/Shelton. As you enter Gorst, exit RIGHT onto Highway 3 South toward Belfair/Shelton. As you approach the Bremerton National Airport, take Exit 28 at SW Barney White Road and enter the Olympic View Industrial Park. At the four-way stop, continue straight through the intersection and follow SW Barney White Road to the next intersection with SW Imperial Way. The Randy W. Casteel Public Works Annex is located on the southwest corner of the intersection.